



## **TO CLEAN A DROP OF PAINT**

### **IF IT IS DRY**

1. Carefully scrape the paint spot with a flat screwdriver to remove dried spot
2. Apply FINISHING OIL on the spot and rub gently in the direction of the grain with a green Scotch Brite pad
3. Wait 5 – 10 minutes then wipe the excess oil with a clean cloth

### **IF IT IS WET**

1. Apply FINISHING OIL on the spot and rub gently in the direction of the grain with a green Scotch Brite pad
2. Wait 5 – 10 minutes then wipe the excess oil with a clean cloth